

DPY Receiving

P.O. Box 6820, Traverse City, MI 49696 1755 Barlow Street, Traverse City, MI 49686 Phone (231) 933-4041 Fax (231) 933-4393


September 12, 2004

VIA Next Day UPS

Permits and Technical Support Unit Groundwater Section-Water Division Michigan Department of Environmental Quality (MDEQ) Constitution Hall P. O. Box 30473 Lansing, MI 48909-7973

Re:

Hydrogeologic Study Report Supplement-Response to June 24, 2004 HS Report Review Williamsburg Receiving and Storage Groundwater Discharge Permit # M 0086 ISE Project #02633061-22E



Dear Mr. Thompson:

In response to your June 24, 2004 letter, please find enclosed the following figures:

- 1. Groundwater Elevation Contour Map
- 2. Clay Surface Structure Contour Map
- 3. Clay Thickness Isopach Map

With respect to the first Map, this rendering excludes the use of groundwater elevations from MW-302 as you recommended. Also excluded is the elevation from MW-102, for the same reasons you cited in your letter. At the MW-102 area, I understand from the owner that seeps have historically been observed at the surface near the southeast corner of the parking lot near the toe of the slope. The anomalously high groundwater elevation in this area suggests an artesian condition affects the groundwater elevation observed at MW-102. Future plots will endeavor to further evaluate this situation.

With respect to the latter two (2) figures, I attempted to include some additional information regarding the local clay horizon from past hydrogeologic investigations at this facility. This is due to the limited number of penetrations of the clay horizon during our study.

Mr. Douglas Thompson September 12, 2004 Page 2 of 2

We will include the additional analytical parameters and MW-302 in quarterly sampling at this site, pursuant to your request. Please call me if you have any questions or comments.

Respectfully submitted,

INLAND SEAS ENGINEERING, INC.

Andrew Smits, P.E.

Environmental Engineering

Department Manager

cc:

Mr. Christopher Hubbell

Mr. Joseph E. Quandt

Mr. Edgar Roy III

Mr. Michael Stifler, PE MDEQ/WD- Cadillac

